

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2344	DATE	June 21, 2016
MANUFACTURER	FCA US LLC (Japanese Importer : FCA Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	Water may travel along the heated power mirror wiring harness and into the heated power mirror electrical connector(s). This can cause corrosion inside the heated mirror connector(s) and the formation of a resistive bridge between the power and ground electrical terminals. A resistive bridge between the power and ground electrical terminals in the heated power mirror connector(s) could cause an electrical fire without warning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-JK38S	Jeep Wrangler	2011Y	104
ABA-JK36S	Jeep Wrangler	2012Y-2013Y	284
ABA-JK38L	Jeep Wrangler Unlimited	2011Y-2013Y	3057
ABA-JK36L	Jeep Wrangler Unlimited	2012Y-2013Y	980
ABA-JK36LR	Jeep Wrangler Unlimited	2013Y	100
Unknown	Jeep Wrangler	2011Y	31
Unknown	Jeep Wrangler Unlimited	2012Y	61
		Total	4617