

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2345	DATE	June 22, 2016
MANUFACTURE	Aston Martin Lagonda Limited (Japanese Importer : Atlantic Cars Limited, Shintoyo Enterprises Ltd, Hakko LR Co., Ltd., M-Auto Co., Ltd.)		
DESCRIPTION OF DEFECT	In the affected models, it is possible that the seat rail can compress the battery supply cable due to inappropriate wiring fixing design. When the damage to the insulation of the cable occurs, it is possible that the excessive electricity conduction in the earth wire inside of seat frame makes a short circuit.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	DBS Coupe	2008-2011	2
	Vanquish Coupe, Vanquish Volante	2012-2015	76
ABA-AM301	Vanquish Coupe	2015-2015	4
TOTAL			82