

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3820	DATE	Jun.1.2016
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the front passenger dual-stage airbag inflator of the subject vehicles, due to insufficient protection against moisture absorption into the propellant, there is a possibility that the propellant could degrade after several years of exposure to temperature and moisture fluctuations. In this condition, the inflator may rupture in the event the airbag is activated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GSE20	[IS250]	2005-2011	30,445
DBA-GSE25			2,848
DBA-GSE20	[IS250C]	2009-2011	2,424
DBA-GSE21	[IS350]	2005-2011	6,641
DBA-GSE21	[IS350C]	2010-2011	320
DBA-USE20	[IS F]	2007-2011	2,638
		TOTAL	45,316