

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ Import Vehicles

CAMPAIGN No.	3823	DATE	Jun. 9. 2016
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	<p>On certain heavy duty trucks equipped with a 12 speed mechanical automatic transmission, due to the inadequate rigidity of the planetary carrier, the pinion shafts may be worn out by the repetition of shift change and the spring pin which fixes the pinion shafts may break, which may cause the pinion shafts to interfere with the main case of the gearbox. Therefore, if it is continued to be used under the condition, an abnormal noise may occur, resulting the vehicle unable to move in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KS-FS1ERWA KS-FS1ERWAKAI	[HINO Profia]	2004~2005	2
KS-FS1EWWA		2004	1
KS-FW1EWWA KS-FW1EWWAKAI		2004~2005	2
BDG-FW1EWYAKAI		2008	1
KS-SH1EFJG		2004	3
ADG-SH1EFXG BDG-SH1EFXG BDG-SH1EFXGKAI		2006~2009	8
BDG-SH1EGXG BDG-SH1EGXGKAI		2007~2008	9
		TOTAL	26