

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	3829	Date	June 27, 2016
Manufacture	CATERPILLAR JAPAN LTD.		
Description of Deffect	Fuel filler opening may be damaged by fuel nozzle contact due to insufficient strength. Then, the unit may have a fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDP-AY4	「910K」	2014, 2015, 2016	1,042
WDP-CD2	「914K」	2014, 2015, 2016	118
		TOTAL	1,160