

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3837	DATE	June 17,2016
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the fuel injector for gasoline engine, there may be a hole at the mesh portion of the filter inside the injector due to inappropriate control of the manufacturing process. As a result, when foreign materials intrude into the injector, engine may become unstable due to misfire caused by insufficient fuel supply as a result of malfunction of the injector. In the worst case, the engine may stall when the vehicle is driven.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-V93W	「PAJERO」	2016	1
		TOTAL	1