

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3838	DATE	June 30, 2016
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the certain passenger airbag inflator, some propellants in inflator may deteriorate due to the prolonged exposure to high absolute humidity, high temperature and high temperature cycling. Therefore, during the airbag deployment, the container of inflator may be broken, components may be scattered, causing passengers to be injured.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABF-SKP2V	Mazda 「BONGO」	2015 - 2016	3,773
ABF-SKP2M		2015 - 2016	1,130
ABF-SKP2T		2015 - 2016	3,546
ABF-SKP2L		2015 - 2016	1,038
DBF-SLP2V		2016	1,551
DBF-SLP2M		2016	620
DBF-SLP2T		2016	1,386
DBF-SLP2L		2016	420
ABF-SKP2VN	Nissan 「VANETTE」	2015	28
ABF-SKP2MN		2015 - 2016	2,012
ABF-SKP2TN		2015 - 2016	3,914
ABF-SKP2LN		2015 - 2016	833
		Total	20,251