

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ Import Vehicles

CAMPAIGN No.	3843	DATE	Jun. 30. 2016
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy duty buses, there are some a crack is generated into the shift unit housing of a transmission because the housing resonates in the specific engine speed region with a high load drive. Therefore, if it is continued to be used under the condition, oil leaks from a crack part, resulting in the seizure of the transmission and the vehicle unable to move in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-RU8JHAA ADG-RU8JHAAKAI BDG-RU8JHAA BDG-RU8JHAAKAI	[HINO SELEGA]	2006~2010	410
LDG-RU8JHBA SDG-RU8JHBA		2010~2015	301
		TOTAL	711