

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3844	DATE	June 30 ,2016
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>On certain heavy duty buses, there are some a crack is generated into the shift unit housing of a transmission because the housing resonates in the specific engine speed region with a high load drive. Therefore, if it is continued to be used under the condition, oil leaks from a crack part, resulting in the seizure of the transmission and the vehicle unable to move in the worst case.</p>	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
ADG-RU8JHAJ BDG-RU8JHAJ	[ISUZU GALA]	2006-2010	155
LDG-RU8JHBJ SDG-RU8JHBJ		2010-2015	199
		TOTAL	354