

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3846	DATE	June. 23. 2016
MANUFACTURER	NIPPON FRUEHAUF COMPANY LIMITED		
DESCRIPTION OF DEFECT	<p>Due to incorrectly spare parts was delivered for wheel bearings, there is a vehicle equipped with a wrong bearings. If the vehicle is continue to use as it is, bearing (separator) is worn and iron powder occurs, bearing grease is early deterioration.</p> <p>In the worst case, bearing is scorched, there is a risk of fire or wheel disengage.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DFPTF341AN (Modified)	Van Semi Trailer	2007	1
DFPTX239A	Semi Trailer	2006	1
DFPVX338A	Semi Trailer	2008	2
DFPVX338B	Semi Trailer	2008	1
DFWDF342C	Van Semi Trailer	2007	1
DFWDF342CN	Van Semi Trailer	2005-2006	4
DFWDF342CN (Modified)	Van Semi Trailer	2009	1
DFWDX342A	Van Semi Trailer	1997	1
DFWFH241A (Modified)	Van Semi Trailer	2001	2
DFWTF241A (Modified)	Van Semi Trailer	2003	1
DFWTF241B (Modified)	Van Semi Trailer	1998-2001	2
KFKDH320S	Container Semi Trailer	2013	1
KFKEX340A	Container Semi Trailer	2006	3
KFKGG340	Container Semi Trailer	1998-2008	4
KFKHG340	Container Semi Trailer	1998-2008	5
RFVDX342B	Van Semi Trailer	2000	1
RFVFX341A	Van Semi Trailer	2012	1
BFDX239B	Dump Semi Trailer	1999	1
		Total	33