

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2346	DATE	26 <sup>th</sup> July 2016
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcyces Japan K.K. )		
DESCRIPTION OF DEFECT	There is a possibility of a fuel leak via fuel pump sub harness because of a problem with the moulding tool used to manufacturer the sub harness. A fuel leak could heighten the risk of fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-GJ900	STREET TWIN	2016	3
		TOTAL	3