

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic (Import Vehicles)

CAMPAIGN No.	GAI-2349	DATE	1 July, 2016
MANUFACTURER	MASERATI S.p.A. (Japanese Importer: Maserati Japan Ltd.)		
DESCRIPTION OF DEFECT	The screws could lose the specific torque value. The vehicle may lose the correct wheel alignment and a noise from the rear could be detected. A sporty continuous use of vehicle with screws not properly tightened may lead to a potential risk of vehicle control loss.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-MQP38A	「Quattroporte」	2013, 2014, 2015	318
ABA-MQP30AA		2013, 2014, 2015	113
ABA-MQP30A		2013, 2014, 2015	387
ABA-MQP30B		2015	41
ABA-MG30AA	「Ghibli」	2013, 2014, 2015	286
ABA-MG30A		2013, 2014, 2015	1,000
ABA-MG30B		2014, 2015	815
		TOTAL	2,960