

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	gai-2352	DATE	Jul 14, 2016
MANUFACTURE	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	Fuel hose may have been fitted the wrong way round on the production line therefore , abnormal wear of the fuel hose due to the contact with the air conditioning pipe.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-KWK4M	「KANGOO」	2009-2014	5715
ABA-KWK4MG	「KANGOO BE BOP」	2010-2011	158
		TOTAL	5873