

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-2354	DATE	8.07. 2016
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF DEFECT	<p>SAFETY RECALL: Certain 2005 through 2014 model year Mustang vehicles built in Flatrock (USA) between April 6th, 2004 through to June 21st, 2014.</p> <p>Our supplier, Takata has determined that the air bag inflator propellant wafers in some inflators may experience an alteration over which could potentially lead to an over-aggressive combustion in the event of an airbag deployment. This potential condition could create excessive internal pressure when the airbag is deployed, which result in the body of the inflator rupturing upon deployment increasing the risk of injury to occupants.</p> <p>Before demonstrating or delivering 2005-2006 Ford GT and 2005-2012 Mustang vehicles, dealers are to replace the driver airbag inflator and return the original inflator for analysis. This service must be performed on all affected vehicles at no charge to the vehicle owner. Parts and repair instruction for 2013-2014 Mustang vehicles are expected to be available in the 4th quarter of 2016.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
	Mustang	2007	657 units
	Mustang	2008	325 units
	Mustang	2009	132 units
	Mustang	2010	228 units
	Mustang	2011	231 units
	Mustang	2012	280 units
	Mustang	2013	218 units
	Mustang	2014	396 units
		TOTAL	2467 units