## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Import Vehicles

CAMPAIGN No.	GAI-2358	DATE	26 <sup>th</sup> July 2016		
MANUFACTURE	Triumph Motorcycles Limited				
	(Japanese Importer : Triumph Motorcyces Japan K.K. )				
DESCRIPTION OF					
DEFECT	Under certain circumstances a dimensional error on the subject aftermarket front				
	brake levers may cause the brake lever blade to contact the handlebar grip before				
	maximum brake performance is achieved. This condition, if present, may lead to longer				
	overall stopping distances in an emergency braking situation, increasing the risk of a				
	crash. (Note that operation of the brake lever in adjustment positions 3, 4, 5 and 6 will				
	avoid the above described handlebar grip contact situation.)				

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
TIPE	NAME	RECALLED	VEHICLE
EBL-GJ900	STREET TWIN	2016	4
		TOTAL	4