

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2365	DATE	2016/7/28
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain V vehicles (Model 447), the brake fluid reservoir may not have been pulled far enough into the intended bracket or may not have been secured correctly due to potentially incorrect installation. As a result, the brake fluid reservoir could work loose from its bracket and fall out. This will result in a loss of brake fluid. It cannot be ruled out that the brake power will deteriorate up to a loss of the brake power as a result of partial or complete emptying of the brake fluid reservoir. This can consequently increase the risk of accident, dependent on the traffic situation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-447811	V220d	2016	1,043
LDA-447815			176
		TOTAL	1,219