

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3847	DATE	Jul.7 2016
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	For the chassis frame of the wheel crane, found that a welded part in between the main member and the cross member might have incomplete penetration, therefore, it might have a crack on the part while driving and when you keep using the crane, it might be caused to breakage of the same at worst.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
WDR-KRC013	KRM - 13H (M)	2016	48	
		TOTAL	48	