## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3848	DATE	July.7.2016	
MANUFACTURER	NISSAN			
DESCRIPTION OF DEFECT	In the Hybrid Power train Control Module (HPCM) of the hybrid car, because the control program of the high voltage cooling system is inappropriate, the temperature such as drive motors etc. may rise when the electric water pump had trouble. For the reason, if the vehicle continues to be driven in this condition, in an extreme case, overheat protection control operates, and an engine and a drive motor stop and the power is not transmitted, and the vehicle might not be able to drive.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-HY51	NISSAN FUGA	$2 0 1 0 \sim 2 0 1 3$	7, 360
DAA-HGY51	NISSAN CIMA	$2\ 0\ 1\ 2\sim 2\ 0\ 1\ 6$	3, 581
DAA-BHGY51	MITSUBISHI DIGNITY		1 1 7
		TOTAL	11,058