

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3853	DATE	July 12, 2016
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Since the electric circuit of the windshield wiper and windshield washer spray of the grader improper, an excessive current may flow into the electric circuit when the windshield washer spray is operated. As a result, the fuse in the electric circuit may blow, and accordingly the windshield wiper and windshield washer spray may be disabled.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-GD032	「GD675-6」	2015 to 2016	24
		TOTAL	24