

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

| | | | |
|------------------------|--|------|--------------|
| Campaign No. | 3854 | Date | July 8, 2016 |
| Manufacture | CATERPILLAR JAPAN LTD. | | |
| Description of Deffect | A hose connecting travel pump and travel motor pad may be damaged due to insufficient manufacturing process. Then, the unit may lose travel / steering function or much oil spread. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---------|-----------------|---------------------|-------------------|
| XDN-H77 | 「907M」 | 2016 | 14 |
| WDP-AY4 | 「910K」 | 2016 | 32 |
| WDP-CD2 | 「914K」 | 2016 | 4 |
| | | TOTAL | 50 |