VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

	200040 10000				
CAMPAIGN No.	3857	DATE	July 20,2016		
MANUFACTURER	Mazda E&T Co.,Ltd.				
DESCRIPTION OF DEFECT	Regarding rear seats of the vehicle with boarding slope device for wheelchair, because installation structure of a fixing band has been insufficient when folding the rear seats, the fixing band may come off the installation part of the rear seats and then the rear seats may fall down. As a result, the rear seats may hit the knee, hand, or other parts of wheelchair users, or the wheelchair users may get injured in the worst case.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
DBA-MK32S (revision)	Suzuki Spacia	2013 – 2016		2,388
DAA-MK42S (revision)	Suzuki Spacia	2015 – 2016		774
DBA-MM32S(revision)	Mazda Flair Wagon	2013 – 2016		529
			TOTAL	3,691