

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3858	DATE	July 12, 2016
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On FSC ( Forward Sensing camera ) equipped on the captioned vehicles, the initial setting of some cameras may not be completed on the inspection process. Therefore, SCBS (Smart City Brake Support system) may not operate normally.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BM5AP	Mazda「Axela」	2016	32
DBA-BM5AS		2016	18
DBA-BM5FP		2016	147
DBA-BM5FS		2016	46
LDA-BMLFS		2016	335
DAA-BYEFP		2016	48
		Total	626