

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3859	DATE	July 22 ,2016
MANUFACTURER	HOWA MACHINERY,LTD.		
DESCRIPTION OF DEFECT	In the hydraulic static transmission (HST) for motor sweeper, due to the unsuitable design of the pulley on the hydraulic pump drive shaft for the drive system, a pulley mounting bolt may not provide sufficient tightening force. Paint peeling from the pulley will further weaken bolt tightening force. In the worst-case scenario, this may cause the pulley to come loose and disable vehicle operations.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
HF64AH	HF64AH	2014 ~ 2016	40
			TOTAL
			40