

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3868	DATE	29-Jul-16
MANUFACTURER	YANMAR CONSTRUCTION EQUIPMENT CO.,LTD.		
DESCRIPTION OF DEFECT	<p>The insufficient manufacturing of front glasses for shovel loaders caused the tiny cracks on its edge and that front glasses were assembled into some machines with its sagging condition. Therefore there is a possibility that the crack may grow and disturb a field of view because of the variation of glass's temperature and the vibration when it's operated.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDM-V37	「V3-7」	2015 to 2016	44
YDM-V47	「V4-7」	2015 to 2016	18
YDM-V57	「V5-7」	2015 to 2016	4
YDM-RW06	「LK40Z-6」	2015 to 2016	4
YDM-RX06	「LK50Z-6」	2015 to 2016	4
TOTAL		2015 to 2016	74

