

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 8 7 0	DATE	Jul.28.2016
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In rear wheel axle, because the shape of the oil seal sealing up the differential gear oil is inappropriate, there is a thing having low seal ability of the axle case and the seal.</p> <p>For this reason, the differential gear oil leaks by the pressure change in the axle and if the vehicle continues to be driven in this condition, the oil ingresses in the rear wheel drum brake inside and if the oil adhere to the brake shoe, the braking force of the rear wheel decreases, in an extreme case, the parking brake might not work in sloping road.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBF-VR2E26	N I S S A N NV350 CARAVAN	2012 ~ 2016	30,725
LDF-VW2E26			22,515
LDF-VW6E26			15,836
LDF-CW4E26			2,297
LDF-CW8E26			5,112
CBF-CS4E26			8,139
CBA-KS2E26			3,850
CBA-KS4E26			1,250
CBF-DS4E26			360
LDF-DW4E26			488
CBF-JVR2E26	I S U Z U COMO	2012 ~ 2016	193
LDF-JVW2E26			610
LDF-JVW6E26			464
LDF-JCW4E26			61
LDF-JCW8E26			63

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBF-JCS4E26	ISUZU COMO	2012 ~ 2016	13
CBF-JDS4E26			1
LDF-JDW4E26			6
		TOTAL	91,983