

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2363	DATE	August 31, 2016
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>The glass panel may have been insufficiently bonded to the sunroof frame in the production process because of dirt on the bonding surfaces. If the glass panel becomes loose when the vehicle is moving, this may endanger road users behind the vehicle.</p> <p>The solar sunroof must be serviced on the affected vehicles in accordance with the Repair Instructions.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-4EBHTF	A8 6.0 Quattro	2007	1
ABA-4EBHTF		2007-2008	9
ABA-4EBPKF	A8 3.2 Quattro	2007	1
ABA-4EBSMF	S8	2007-2009	186
ABA-4EBVJF	A8 4.2 Quattro	2007	49
ABA-4EBVJL	A8 4.2 Quattro LWB	2007-2008	28
		Total	274