

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	3872	DATE	26 AUG. 2016
MANUFACTURE	MARUYAMA MFG.CO.,INC		
DESCRIPTION OF DEFECT	In the agricultural chemical spray vehicles, there are some vehicles that have a defect in the wiring of reversing lamp switch. When operating a gear lever, wiring may cause broken. When doing sternway, there is a possibility that reversing lamp doesn't light up.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MARUYAMA S Z 54	SSA-Z500	2013 ~ 2014	263
	3S-H500		
		TOTAL	263