

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	3873	DATE	26 AUG. 2016
MANUFACTURE	MARUYAMA MFG.CO.,INC		
DESCRIPTION OF DEFECT	In the agricultural chemical spray vehicles, there are some vehicles that have a defect in fuse board location which tends to be splashed by the water. When water permeates and corrodes in the fuse, it may cause broken of the fuse. Then, there is the possibility that the vehicle lose braking ability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MARUYAMA S Z 54	SSA-Z500 SSA-Z601 S SSA-Z500-1 SSA-Z500-2 SSA-Z601S-1	2013 ~ 2016	628
	3S-H500 3S-H620		
		TOTAL	628