

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3876	DATE	Aug.23 2016
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty tractor, improper fan shaft pulley bearing is used in the cooling system, which may cause the fan shaft tilt during high speed driving. This may result in poor sealing of the pulley bearing, flowing out the grease in the pulley, and the poor lubrication due to this leakage will lead to abnormal wear of the pulley bearing, resulting in seizure of the bearing. In the worst case, the cooling fan may interfere with the radiator, which may cause leakage of coolant, and the vehicle may become unable to operate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-FV50VJR	「FUSO SUPER GREAT」	2011~2012	185
QDG-FV50VJR		2011~2015	1,075
QKG-FV50VJR		2013~2014	3
QKG-FV60VJR		2014~2016	488
QKG-FV64VJR		2014~2016	36
QPG-FV64VJR		2014~2016	21
		TOTAL	1,808