

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3880	DATE	Aug.23 2016
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some medium-duty trucks equipped with discharge headlights, pin layout of the height sensor (which detects the attitude of the rear of the vehicle) is incorrect and the sensor is inoperative. Because of this, the automatic leveling system of the discharge headlights may not function at rough road driving, etc.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-FQ62F	「FUSO FIGHTER」	2012～2016	797
QKG-FK62FZ		2012～2016	2,083
QKG-FK72FZ		2012～2016	489
TKG-FK61F		2012～2016	4,788
TKG-FK62FY		2012～2016	514
TKG-FK71F		2012～2016	1,585
TKG-FK72FY		2012～2016	251
		TOTAL	10,507