

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-2340	DATE	Sep. 27, 2016
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF DEFECT	Compliance Recall - Certain 2013 to 2014 Model Year Mustang Vehicles built in Flatrock, USA, between April 13, 2012 and May 16, 2014. On some of the affected vehicles, one or both rear lamp assemblies may cause the turn indicator system to erratically "flash fast" attempting to alert the driver of rear lamp failure, when lamp failure is not actually present. This inconsistent flashing speed does not conform to the requirements specified by Japanese regulations. (Technical Standard for Installation of Lamps, Reflex Reflectors and Direction Indicator Lamps) section 4-6-9-1 regarding direction indicator lamp flashing speed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	Mustang	2013-2014	614 units
TOTAL			614 units