

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2372	Date	September 7, 2016
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper hole creating for fuel pipe attachment in cylinder head, diameter of the hole might be large. As a result, the thread would not be processed correctly and tightening force of the fuel pipe mounting bolt would not be enough. By continuous use, fuel pipe will be loosened by driving vibration and fuel leaks, in the worst case it leads to fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-16CPL	VW The Beetle 2.0T	MY2016	2
		Total	2