

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2373	DATE	Sep. 21, 2016
MANUFACTURER	Bentley Motors Limited (Japanese Importer : Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	On the sunroof glass fitted with a solar cell, adhesive force between the sunroof glass and its frame is lower due to incorrect manufacturing process. Therefore the sunroof glass may be detached by wind pressure whilst driving when adhesive force becomes lower in use.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-BSBWR	Continental Flying Spur	2007 – 2008	7
		TOTAL	7