

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2378	DATE	2016/9/15
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On the CLA and A-Class vehicles (model series 117, 176) with AMG engines, a potentially defective welding seam between the disk and hub on a clutch may evolve into a crack. In case of a crack of the welding seam there would be no traction at this clutch. The gearbox could then either shift into 'neutral' or fall back into a partial gearbox limp home mode. In case of a shift into 'neutral' there would be no torque on the power train and the vehicle would coast to a stop.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-176052	Mercedes-AMG A45 4MATIC	2016	1
CBA-117352	Mercedes-AMG CLA45 4M	2016	1
CBA-117952	Mercedes-AMG CLA45 4M SB	2016	3
TOTAL			5