

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 8 9 8	DATE	Sep.16.2016
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In the generator with the starter for the vehicle with the stop-start system, because the tolerance of the electric circuit is insufficient, an internal part may be damaged by the high electric current when the engine restarts. Therefore, the circuit short-circuits and the engine cannot restart, and In an extreme case, the circuit generates heat by the short-circuit and the generator might be burned.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-GFC27	SERENA	2016	218
DAA-GFNC27			13
DAA-GC27			57
DAA-GNC27			12
		TOTAL	300