

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3889	DATE	September.8. 2016
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>In certain the passenger's airbag inflators, gas generating propellant may get deteriorated through repetition of environmental temperature and humidity fluctuations. This can, in the event of the airbag deployment, cause abnormal rise in internal pressure of the inflator whereby the container of inflator could be broken.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GE6	「FIT」	2010～2011	200,522
DBA-GE7			15,137
DBA-GE8			42,137
DBA-GE9			3,209
DAA-GP1			113,239
DBA-GG7	「FIT SHUTTLE」	2011	6,744
DBA-GG8			1,263
DAA-GP2			29,803
DBA-GB3	「FREED」 「FREED SPIKE」	2010～2011	138,159
DBA-GB4			11,506
DAA-GP3			17,358
DAA-ZE2	「INSIGHT」	2010～2011	41,045
DAA-ZE3	「INSIGHT EXCLUSIVE」	2011	1,577
DBA-FD1	「CIVIC」	2009～2010	1,593
DBA-FD2			543
ABA-FD2			4,333
DAA-FD3			8,388

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-RR1	「ELYSION」 「ELYSION PRESTAGE」	2009～2011	9,216
DBA-RR2			1,219
DBA-RR3	「ELYSION」	2009～2010	545
DBA-RR4			185
DBA-RR5	「ELYSION PRESTAGE」	2009～2011	808
DBA-RR6			229
DBA-RE3	「CR-V」	2010～2011	3,304
DBA-RE4			3,021
DBA-CU1	「ACCORD」	2011	1,169
DBA-CU2		2009～2011	3,456
DBA-CW1	「ACCORD TOURER」	2011	985
DBA-CW2		2009～2011	3,648
DBA-CP3	「INSPIRE」		3,360
DBA-KB2	「LEGEND」		1,107
ZBA-ZC3	「FCX CLARITY」	2009～2010	8
		TOTAL	668,816