

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2370	DATE	Oct 13, 2016
MANUFACTURE	Harley-Davidson Motor Company (Japanese Importer : Harley-Davidson Japan K.K.)		
DESCRIPTION OF DEFECT	Harley-Davidson Motor Company, Inc. has decided that the hydraulic clutch system with black master cylinder part numbers 36700049B, 36700056B, 36700146 and 36700186 on certain model year 2016 Touring and Softail model may exhibit a condition in which it may lose the ability to generate enough lift to disengage the clutch after being parked for an extended period. If this condition remains undetected, it could lead to a loss of control of the vehicle when started in gear or first shifted into gear.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-FLHL	ULTRA LIMITED	2016	15
EBL-FLHL	ROAD GLIDE URTRA	2016	79
EBL-FLHL	URUTRA LIMITED LOW	2016	60
EBL-FLHM	STREET GLIDE SPECIAL	2016	252
EBL-FLHM	ROAD GLIDE SPECIAL	2016	201
EBL-FLN	CVO STREET GLIDE	2016	204
EBL-FS9	CVO PRO STREET BREAKOUT	2016	335
EBL-FS9	SOFTAIL SLIM S	2016	363
EBL-FS9	FAT BOY S	2016	290
		TOTAL	1799