

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2385	DATE	Oct. 17 <sup>th</sup> , 2016
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The ISOFIX child seat fixing brackets on the rear seats are not enduring enough. Thus, when driving with the child seat mounted, repeated loading might cause crack on the fixing bracket by metallic fatigue. When keep driving under such condition, the fixing bracket might break, and the child seat might not be attached or might come off, in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-WX20	BMW X3 xDrive 20i	2011 - 2016	2,403
DBA-WX20	BMW X3 xDrive 28i	2012 - 2016	639
LDA-WY20	BMW X3 xDrive 20d	2012 - 2016	9,017
CBA-WX30	BMW X3 xDrive 28i	2010 - 2012	1,001
DBA-WX35	BMW X3 xDrive35i	2010 - 2016	1,472
DBA-XW20	BMW X4 xDrive 28i	2014 - 2016	1,110
DBA-XW35	BMW X4 xDrive 35i	2014 - 2016	609
DBA-XW35M	BMW X4 M40i	2015 - 2016	39
		TOTAL	16,290