

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	gai-2388	DATE	Oct,31, 2016
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer : DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	<p>The damper plate assembled between the primary driven gear and the clutch basket assembly, could brake due fatigue failure.</p> <p>If damper plate breaks, part of the damper plate assembly can lost their position and can block the engine.</p> <p>Authorized Ducati dealers will replace the clutch assembly with a new redesign component supplied by Ducati warehouse.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZDMH808JAEB	1199Superleggera	2014	32
		TOTAL	32