

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2391	DATE	Oct. 17 <sup>th</sup> , 2016
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	The ISOFIX child seat fixing brackets on the rear seats are not enduring enough. Thus, when driving with the child seat mounted, repeated loading might cause crack on the fixing bracket by metallic fatigue. When keep driving under such condition, the fixing bracket might break, and the child seat might not be attached or might come off, in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
FDA-PP10	XD3 Biturbo	2015	38
		2016	31
		TOTAL	69