

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2395	DATE	October 28, 2016
MANUFACTURER	FCA US LLC (Japanese Importer : FCA Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	The power liftgate control module may experience a corrosion induced high resistance short circuit in the power liftgate module electrical connector(s). The power liftgate module electrical connector(s) could allow water intrusion and cause the module to become inoperative and/or cause a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-KL24	Jeep Cherokee	2014	182
ABA-KL32	Jeep Cherokee	2014	329
ABA-KL32L	Jeep Cherokee	2014	240
ABA-KL24	Cherokee	2014-2015	146
ABA-KL32	Cherokee	2014	149
ABA-KL32L	Cherokee	2014-2015	67
ABA-KL24P	Cherokee	2015	153
Total			1,266