

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI-2402	DATE	October 28, 2016
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation)		
DESCRIPTION OF DEFECT	With regards to vehicles equipped with the EVSC (Electronic Vehicle Stability Control) system for Heavy Duty Tractors, the ESP (Electronic Stability Program) indication lamp may not flash properly upon activation of the ESP and/or light up upon malfunction of the ESP (both of which are part of the device's indication lamp performance requirements), due to the ESP's inappropriate parameter setting (Warning display function). As such, the indication lamp may be in non-conformance with the Japan Safety Regulation Article 12, Details of Safety Regulations, Article 15 (Regulation No. 13. 11 series of amendments). Notwithstanding the forgoing, the healthy functioning of the braking devise and ESP are not affected by the above.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-H2TDA1	FH	2015-2016	2
Unspecified		2015-2016	3
		TOTAL	5