

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	3904	DATE	October 21, 2016
MANUFACTURER	SUMITOMO NACCO FORKLIFT CO., LTD. (Japan)		
DESCRIPTION OF DEFECT	<p>① The heat resistance of the brake piston seal is insufficient. Therefore, the seal may be damaged by heat, in the worst case, the brake force may become ineffective owing to brake fluid leakage.</p> <p>② The spider pin in differential may be worn under heavy duty usage owing to improper design. Therefore, the seal of brake piston may be damaged by the contamination from the differential, in the worst case, the brake force may become ineffective owing to brake fluid leakage.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
XDN-D4K	FD40PXII	2015~2016	3 (① 0, ② 3)
XDN-D4L	FD45PXII FD50PXII	2015~2016	12 (① 3, ② 12)
		TOTAL	15 (① 3, ② 15)