

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3905	DATE	Oct.12.2016
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the Parking Brake System of the subject vehicles, due to improper fixing of the parking brake cable, there is a possibility that the cable could disengage from the crank lever by vehicle vibration, causing the parking brake to become inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-ZVW50	[PRIUS]	2015-2016	101,554
DAA-ZVW51			73,378
DAA-ZVW55			37,558
		TOTAL	212,490