

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ Import Vehicles

CAMPAIGN No.	3906	DATE	Oct. 17. 2016
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy duty trailer tractors, due to the improper tightening work of front brake hoses, there are some that the tightening torque of the nuts at the hose connecting parts is insufficient. Therefore, the nuts at the hose connecting parts may be loosen, causing the brake air to leak, resulting the braking force to decline in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QPG-SH1EDDG	[HINO Profia]	2016	31
QPG-SH1EDDJ			
QPG-SH1EEDG		2016	4
QKG-SH1EGDG		2016	4
QDG-SS1EKDA		2016	6
QPG-SS1EKDG			
		TOTAL	45