

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3 9 0 7	DATE	1 2 October, 2016
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO. LTD.		
Causes and situations where the structure, device, or capacity is determined to be non-compliant with standards	As the mirror bracket on the under mirror that is used for confirming the vehicle carrier is housed in its traveling position is of an inappropriate design, cracking of the welding points can occur from vibrations during travel. If use is continued in this state, these cracks will further progress, and in the worst case, the mirror could fall off causing problems for other vehicles on the road.		

MANUFACTURER'S NAME	TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MITUBISHI FUSO	TKG-FEB50	CANTER	2015-2016	27
	TKG-FEB80	CANTER	2015-2016	13
	TKG-FEB90	CANTER	2015	2
	TKG-FEC90	CANTER	2015	1
	TKG-FK61F	FIGHTER	2015	1
ISUZU	TRG-NPR85AN	ELF	2015-2016	32
	TPG-NPR85YN	ELF	2015	4
	TKG-FRR90S2	FORWARD	2015-2016	3
TOYOTA	TDG-XZU720	DYNA	2015-2016	8
	TKG-XZU720	DYNA	2015	2
	TKG-XZU720	TOYOACE	2015-2016	20
	TKG-XZU775Modify	TOYOACE	2016	1
HINO	TDG-XZU720M	DUTRO	2015-2016	8
	TKG-XZU720M	DUTRO	2015-2016	8
	TKG-FC9JHAA	RANGER	2015	3
	TKG-FC9JHAP	RANGER	2015	1
	TKG-FD7JJAA	RANGER	2015-2016	3
MAZDA	TRG-LPR85AN	TITAN	2015	2
	TPG-LPS85AN	TITAN	2015	1
NISSAN	TPG-FEB8W	ATLAS	2016	1
			TOTAL	141