

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3909	DATE	Oct.20 2016
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some rear tandem-axle heavy-duty tractors, tightening torque for the bolts fixing the ring gear of the differential is insufficient because improper sockets were used on the bolt tightening machine. If the vehicle is continued to be used in this condition, the bolts may become loose and, in the worst case, they may fall off and damage the differential, making the vehicle unable to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-FV60VJR	「FUSO SUPER GREAT」	2015~2016	315
		TOTAL	315