

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3912	DATE	October. 26. 2016
MANUFACTURER	TOYOTA AUTO BODY CO.,LTD		
DESCRIPTION OF DEFECT	Due to improper production of “steering yoke” which is the part connecting steering wheel with steering gear box, more play is possibly given to the engagement between steering yoke and steering gear box. The steering yoke can be worn in continuous use on the above condition, in the worst case the steering wheel will be unable to steer the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TAK30	COMS	2012~2016	4,520
—	COMS	2013~2015	11
		TOTAL	4,531