

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

|                       |   |      |                  |
|-----------------------|---|------|------------------|
| CAMPAIGN No.          | 3916  | DATE | October 27, 2016 |
| MANUFACTURER          | Mazda Motor Corporation   |      |                  |
| DESCRIPTION OF DEFECT | On the fuel tank, due to insufficient performance of heat resistance on top of the fuel tank, the pump rings may be deteriorated by exposure to heat from the engine and exhaust pipe. Therefore, continuous use may lead to deterioration, the pump rings may eventually crack and fuel leakage may occur, in the worst case, resulting in a fire. |      |                  |

| TYPE                | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---------------------|-----------------|---------------------|-------------------|
| LA-SE3P<br>ABA-SE3P | Mazda「RX-8」     | 2003-2008           | 30,753            |
|                     |                 | Total               | 30,753            |