

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-2386	DATE	22/November/2016
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	The right side silencer may break apart from the exhaust pipe at the weld. The exhaust pipe steel grade contains insufficient percentage of Titanium resulting in poor weld quality. The corrective action is to replace both rear silencer.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[S80]	2015	4
	[XC70]	2015	19
		TOTAL	23